

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director

FILE COPY

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

September 13, 2006

Theresa Wessels, Administrator Juniper Meadow, Emeritus Properties II, Inc 2975 Juniper Dr Lewiston, ID 83501

License #: RC-595

Dear Ms. Wessels:

On August 9, 2006, a survey was conducted at Juniper Meadow, Emeritus Properties II, Inc. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Eric Mundell, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

ERIC MUNDELL

Team Leader

Health Facility Surveyor

Facility Fire, Life Safety, and Construction Program

EM/slc



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

August 23, 2006

Theresa Wessels, Administrator Juniper Meadow, Emeritus Properties II 2975 Juniper Dr Lewiston, ID 83501 FILE COPY

Dear Ms. Wessels:

On August 9, 2006, a Life Safety Code survey was conducted at Juniper Meadow, Emeritus Properties Ii, Inc. The facility was found to be providing a safe environment and safe, effective care to residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by September 8, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

JAMIE SIMPSON, MBA, QMRP

Supervisor

Residential Care Assisted Liviing Program

JS/slc

Enclosure

PRINTED: 08/15/2006 FORM APPROVED Bureau of Facility Standards (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - ENTIRE BUILDING A. BUILDING B. WING_ 08/09/2006 13R595 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2975 JUNIPER DR JUNIPER MEADOW, EMERITUS PROPERTIES LEWISTON, ID 83501 PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE (EACH DEFICIENCY MUST BE PRECEEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R9999 R9999 Initial Comments The facility was found to be in substantial compliance with the fire and life safety standards of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on August 9, 2006. The surveyors conducting the survey were: Eric Mundell REHS Team Leader Health Facility Surveyor Taylor Barkley Health Facility Surveyor

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

4LUR21



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Jun. per Mendows Emeritus	2975 Juniper Drive	746-8676
Administrator ¹	City	ZIP Code
Theresa Wends	belevister	83501
Survey Team Leader	Survey Type	Survey Date
Evil Mundell	I FLS	8/9/06

(armir	the state of the s		
NON-(ORE ISSUES		
ITEM	RULE#	DESCRIPTION	DATE
#			RESOLVE
	16.03.22.404.01	Fire and Life Safety Standards: (a) The south, contrat and	
		east stair wells had combustible materials stored under	
		the Star wells (b) Vertical separation was incomplete	1
		between the 19th and 2nd flowers. Panic hard ware was	
		pinned open and the sloors would not latch at both	
;		the upper and lower levels. East, west and south	
		stairwell doors ded not latch; vertical separation was	
		incomplete as was separation of the starruelle from	
		The corridors (C) The crosscarridor dears for the second	
		and first fleers did not completely close and latch, re-	
****		Spectively @ Escutaeun plate meining above consider sprinkly-South exitous	
2	16.03.22.405.	b. Electrical Installations: A multiple weld festensions cord	:
	>-	basin use in the willness room to power a computer and	
2.00		the call system monitor.	
3	16.03.72.750.	01 Fire Dr. 115: Documentation, for fire dills, held for one pershyt	
-		Dur quarter was not maintained on life.	
Response	Required Date	'Signature' of Facility Representative	
Stinke	~ 9,200kg	X Thornes 1 Marcal Experience of Main to	